SGS

Received: **Tested For: Supplied by: Vyva Fabrics** Phone: 3/7/2022 TT. Vasumweg 140 Fax: **Completed:** 3/11/2022 1033 SH, Amsterdam Code: Mobile: Ζ The Netherlands 3-47151-0 PO#: 122503 **Test Report: Key Test:** BS EN 1021-1: 2014 355 **Client's Identification:** Style: Econic. Composition: PVC / Recycled Polyester. Weight: 31 oz/54". Thickness: 42 mil. Product End Use: Upholstery. LE 2014; V 7/21 DK PC: 24H /rb /dv TEST PERFORMED: British Standard BS EN 1021-1: 2014 - Furniture - Assessment of the Ignitability of Upholstered Furniture, Part 1 IGNITION SOURCE: Smouldering Cigarette SRM 1196a **TEST ITEM COMPOSITE:** Client's Cover Fabric: (see "Client's Identification" section above) Suggested Filling Material: Non flame retardant flexible polyether foam, 20-24 kg/m³ Flame retardant polyurethane foam, 45 kg/m² (2.8 lbs./ft²), Code Red II 35 Non-flame retardant flexible polyether foam, 20-24 kg/m³, wrapped with Sandel Style 12701-14502 fire blocking material $(4.7 \pm 0.5 \text{ oz/yd}^2)$ COVER FABRIC WATER SOAKED PRIOR TO TESTING IN ACCORDANCE WITH ANNEX D: ☐ Yes: ☒ No PRECONDITIONING: 24 hours at 23°C \pm 2°C (73.4°F \pm 2°F) and 50% \pm 5% RH BRIEF DESCRIPTION OF TEST: Test cushions are placed in a test frame to form a mockup of an upholstered chair. A lighted cigarette is placed in the crevice formed by the seat and back cushion. Test observations are made, and results are recorded.

JG Ver. 2021-03-09 10:35 Page 1 of 3

The results contained in this report relate only to the item(s) tested. The test report shall not be reproduced except in full, without written approval from SGS North America.

This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at http://www.sgs.com/en/Terms-and-Conditions/terms-e-document.aspx. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for a maximum of 45 days only.



Tested For: Supplied by: Vyva Fabrics Phone: Received: 3/7/2022

1033 SH, Amsterdam Mobile: Code: Z

The Netherlands PO#: 122503 Test Report: 3-47151-0

Key Test: BS EN 1021-1: 2014

		DETAILED RESULTS			
		Initial Test	Repeat Test		
All smouldering (heat, smoke, or glowing) ceased after	[mm:ss]:	23:40	25:16		
Furthest extent of smouldering/flaming					
Left of ignition source	[mm]:	3	3		
Right of ignition source	[mm]:	1	1		
Forward of ignition source	[mm]:	3	4		

	SUMMARY RESULTS		
IGNITION CRITERIA:	Initial Test (yes/no)	Repeat Test (yes/no)	
Smouldering			
Unsafe escalating combustion (3.1a):	No	No	
Test assembly consumed (3.1b):	No	No	
Smoulders to extremities (3.1c): [Left 190mm, Right 190mm, Forward 225mm]	No	No	
Smoulders through thickness (3.1c):	No	No	
Smoulders more than 1 hour (3.1d):	No	No	
Smoulders, where upon final examination, evidence of active smouldering was apparent after the test specimen was dismantled and examined internally (3.1e, 9.3):	No	No	
Flaming			
Occurrence of flames (3.2):	No	No	

SUMMARY RESULTS EXPLAINED: If "Yes" is entered for any category, the report must conclude that ignition did occur.

JG Ver. 2021-03-09 10:35 Page 2 of 3

The results contained in this report relate only to the item(s) tested. The test report shall not be reproduced except in full, without written approval from SGS North America.

This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at http://www.sgs.com/en/Terms-and-Conditions/terms-e-document.aspx. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for a maximum of 45 days only.

Supplied by: Vyva Fabrics Tested For: Phone: Received: 3/7/2022

Mobile:

TT. Vasumweg 140 Fax: **Completed:** 3/11/2022 1033 SH, Amsterdam

Code:

Ζ

The Netherlands 3-47151-0 PO#: 122503 **Test Report:**

Key Test: BS EN 1021-1: 2014 355

ABBREVIATIONS WHICH MAY BE USED:

N/O = Not observed. NT Not tested.

EC Escalating combustion (unsafe); test extinguished by technician at time noted.

COMMENTS:

\times	Replacement	cigarette(s)	not needed	as all cigarettes	burned their	complete	length.

☐ Replacement cigarette used on: ☐ initial test; ☐ repeat test

CONCLUSION: The above Results indicate that:

☑ Ignition Criteria did not occur (favourable)

☐ Ignition Criteria did occur (unfavourable)

Note: The subject test measures whether or not ignition occurs. The codes speak in terms of ignition resistance. Therefore, the conclusion "Ignition Criteria did not occur" is a favourable conclusion; and "Ignition Criteria did occur" is not a favourable conclusion.

PROVISO: The test conducted herein is based on a prototype composite using a candidate upholstery covering fabric and a standard filling material. The results displayed by the candidate upholstery fabric may differ when used in an actual item of upholstered furniture, since other variables may affect the fire performance properties. Other variables may consist of different filling materials; fire blocking materials; furniture geometry; and other furniture components.

The above test results relate only to the ignitability of the combination of materials under the particular conditions of test; they are not intended as a means of assessing the full potential fire hazard of the materials in use.

CERTIFICATION: I certify that the above results were obtained after testing specimens in accordance with the procedures and equipment specified above.

DocuSigned by:

Bobby Brown

-B50EB94D593C454...

3/15/2022

AUTHORIZED SIGNATURE SGS NORTH AMERICA

/dv /tc

JG Ver. 2021-03-09 10:35 Page 3 of 3

The results contained in this report relate only to the item(s) tested. The test report shall not be reproduced except in full, without written approval from SGS North America.

This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at http://www.sgs.com/en/Terms-and-Conditions/terms-e-document.aspx. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for a maximum of 45 days only.